IPS e.max CAD

Characterization Process

1

Preparing the restoration

Object Fix

Flow (shown) will be used to affix the restoration to the firing pin for characterization and firing. Object Fix - Putty can also be used

Crystallization Tray

After characterization place the restoration onto the crystallization tray for firing. Note there is an additional Speed Crystallization Tray for IPS e.max

2

Characterization of IPS e.max





3

Oven program and firing

Information bar
Indicates current furnace temp and selected furnace programs

Main screen
Indicates the selected firing program, firing progress, and other menu options

Navigation bar
Browse between programs and settings

Program Information

Check your oven's User Manual for program information.

QUESTIONS? Contact CAD/CAM Support @ (800) 537 6070

PMCA-EDU-IG0006A 09/20

PLANMECA